


T303TS (38000001-)



## Documents

- 01\_CYLINDER\_\_PISTON\_\_CRANKSHAFT
- 02\_CRANKCASE
- 03\_MAGNETO
- 04\_CLUTCH
- 05\_AIR\_CLEANER\_\_CARBURETOR
- 06\_Carburetor
- 07\_FUEL\_TANK
- 08\_MUFFLER
- 09\_RECOIL\_STARTER\_\_PULLY
- 10\_GEAR\_CASE\_\_SHIELD
- 11\_MAIN\_PIPE\_\_HANDLE
- 12\_THROTTLE
- 13\_ACCESSORIES

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 01\_CYLINDER\_PISTON\_CRANKSHAFT

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A011001540	Crankshaft, SRM-3020TES		Slow-moving
2	1	A130002350	Cylinder SRM-3020TES		Slow-moving
3	1	V100000870	GASKET,CYL		Medium-moving
4	4	V805000210	BOLT, TORX 5		Slow-moving
5	1	P100005250	PISTON KIT		
6	2	A101000740	RING, PISTON		Medium-moving
7	1	10001327430	PIN, PISTON		Slow-moving
8	2	10001453630	SPACER, PISTON PIN		Slow-moving
9	1	10001216131	BEARING, NEEDLE		Slow-moving
10	2	10001503931	CIRCLIP, PISTON PIN		Slow-moving
11	1	V485003060	LEAD		Slow-moving
12	1	A160003480	Cylinder cover, C302TS		Slow-moving
13	1	X562001960	LABEL,SHINDAIWA		Slow-moving
14	1	X524001901	LABEL		Slow-moving
15	1	V203002550	Screw M5x12		Slow-moving
16	1	V203002550	Screw M5x12		Slow-moving
17	1	A160003470	COVER,CYLINDER		Slow-moving
18	1	V805000140	BOLT, TORX 5		Slow-moving


www.emc-motoculture.com



## Illustration 02\_CRANKCASE

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100005260	Crankcase complete, SRM-3020TES		
2	1	9403536201	BEARING, BALL		
3	1	90070200032	CIRCLIP 32		
4	1	10021203930	OILSEAL		Slow-moving
5	1	9403536201	BEARING, BALL		
6	1	10021305530	OILSEAL		Slow-moving
7	1	V102000310	GASKET,CRANKCASE		Medium-moving
8	3	V805000220	BOLT, TORX 5		Slow-moving

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 03\_MAGNETO

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A409001350	ROTOR, MAGNETO		Slow-moving
2	1	A411001780	Ignition Module, SRM-3020TES	Y2024-763	Slow-moving
3	1	90051500008	NUT, FLANGE 8		
4	2	V323000130	WASHER,CIRCULAR 5		Slow-moving
5	2	V835000030	BOLT, TORX 5		Slow-moving
6	1	10014212330	KEY, WOODRUFF		Slow-moving
7	1	A425000060	SPARKPLUG		Fast-moving
8	1	A427000090	PLUG CAP		Slow-moving
9	1	V151000170	PLATE,CUP		Slow-moving
10	1	A429000110	PLUG CAP COVER		Slow-moving
11	1	J473000120	PIECE,COVER		
12	1	90072000022	O-RING 22		
13	1	15901103432	COIL, SPARK PLUG		Slow-moving
14	1	V475007550	TUBE		Slow-moving
15	1	V485003050	LEAD		Slow-moving


www.emc-motoculture.com



## Illustration 04\_CLUTCH

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100005270	CLUTCH SHOE SET		
2	1	A566000330	SPRING, CLUTCH		Medium-moving
3	2	17504656030	SHAFT, CLUTCH		Medium-moving
4	2	17504956030	WASHER		Slow-moving
5	2	17504805530	WASHER (I)		Slow-moving
6	1	P100005280	housing, clutch cpl. with clutch drum, SRM-3020TES		
7	1	A172003410	Clutch housing SRM-3020TES		Slow-moving
8	2	90033040080	ROLLER		
9	2	90080706001	BEARING, BALL 6001		
10	1	A556001820	Clutch drum SRM-3020TES		Medium-moving
11	1	90070200028	RETAINING RING		
12	1	90070100012	CIRCLIP 12		
13	1	A413000130	Protection C302TS		Slow-moving
14	4	V805000160	BOLT, TORX 5		Slow-moving
15	1	V420000970	CUSHION		Medium-moving
16	1	V805000170	BOLT, TORX 5		Slow-moving
17	1	90070200045	RING, RETAINING(IN)		
18	1	V805000140	BOLT, TORX 5		Slow-moving

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 05\_AIR\_CLEANER\_\_CARBURETOR

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A202000330	BELLOWS, INTAKE		Slow-moving
2	1	A206000060	HOLDER, BELLOWS		Slow-moving
3	2	V805000150	BOLT, TORX 5		Slow-moving
4	1	A209001080	PLATE, INSULATOR		Slow-moving
5	3	V805000000	BOLT, TORX 5		Slow-moving
6	1	A209001090	PLATE, INSULATOR		Slow-moving
7	1	V103002010	Gasket carburetor to intermediate flange, SRM-3020TES		Fast-moving
8	1	A021004831	CARBURETOR,DIAPHRAGM		Medium-moving
9	1	V103001900	GASKET,INTAKE		Fast-moving
10	1	P021051160	CLEANER CASE ASY		
11	1	A244000370	PLATE,PREVENT		Slow-moving
12	2	V805000340	BOLT, TORX 5		Slow-moving
13	1	A232001970	Air filter cover, SRM-3020		Slow-moving
14	2	V299000640	KNOB,FASTENER		Slow-moving
15	2	V340000210	WASHER		Slow-moving
16	1	89033252730	LABEL, CHOKE		Slow-moving
17	1	A227000050	PLATE, ELEMENT		Slow-moving
18	1	A226002030	ELEMENT, AIR FILTER		Fast-moving
19	1	A226002040	ELEMENT, AIR FILTER		Fast-moving


www.emc-motoculture.com



## Illustration 06\_Carburetor

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A021004831	CARBURETOR,DIAPHRAGM		Medium-moving
2	1	P003006120	BODY ASSEMBLY, PUMP		
3	1	12317307930	CLIP		Slow-moving
4	1	12314203930	COVER, M. DIAPHRAGM		Slow-moving
5	1	P003006500	COVER, FUEL PUMP		#N/A
6	1	P003006130	VALVE, THROTTLE		
7	1	P003004480	O-RING		
8	1	P003005850	SWIVEL		
9	1	12313719830	VALVE, INLET NEEDLE		Slow-moving
10	1	P003004530	GASKET, FUEL PUMP		
11	1	12314027230	GASKET,M. DIAPHRAGM		Fast-moving
12	1	P003004540	DIAPHRAGM, FUEL PUMP		
13	1	P003001670	DIAPHRAGM, METERING		
14	1	P003005860	SCREW		
15	4	P003004560	SCREW		
16	4	P003004570	SCREW		
17	1	P003005870	SPRING		
18	2	P003001710	WASHER		
19	1	P003005880	NEEDLE		Slow-moving
20	1	12312610631	SCREEN, INLET		Medium-moving
21	1	12313803930	PIN, METERING LEVER		Slow-moving
22	1	P003001630	LEVER, METERING		
23	1	12318109560	PUMP, PRIMER		Fast-moving
24	1	P003005890	CLIP		
25	3	12311440630	SCREW		Slow-moving
26	1	P003005900	PLATE		


www.emc-motoculture.com



## Illustration 07\_FUEL\_TANK

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A350002500	Fuel tank, SRM-3020TES		Slow-moving
2	1	P021035681	FUEL CAP ASY		
3	1	V107000190	GASKET,FUEL CAP		Fast-moving
4	1	A365000060	CONNECTOR,CAP		Medium-moving
5	1	13211555931	GROMMET, FUEL		Slow-moving
6	1	V471001201	PIPE		Slow-moving
7	1	V470002361	Suction hose, fuel, rubber, C303TS 3x5x140x35		Slow-moving
8	1	V186000500	JOINT,PIPE		Slow-moving
9	1	V490001240	CLIP		Slow-moving
10	1	V471003321	Line, petrol (rubber), SRM-3020TES 3x6x95		Slow-moving
11	1	13201049730	PIPE 3*6*85		Slow-moving
12	1	A356000031	VALVE,CHECK		Medium-moving
13	1	V490001230	CLIP		Slow-moving
14	1	A369000470	STRAINER, FUEL		Fast-moving
15	1	V490001240	CLIP		Slow-moving
16	1	A175000400	Tank protection, SRM-3020TES		Slow-moving
17	2	V805000230	BOLT, TORX 5		Slow-moving
18	2	V805000160	BOLT, TORX 5		Slow-moving
19V	1	A413000190	BOOT		Slow-moving

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 08\_MUFFLER

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100005300	Exhaust complete, SRM-3020TES	Y2024-763	
2	1	A313002080	GUIDE, EXHAUST		Slow-moving
3	1	14586240630	SCREEN, MUFFLER		Medium-moving
4	1	V104002380	Gasket, exhaust SRM-3020TES		Fast-moving
5	3	V804000030	BOLT, TORX 4		Slow-moving
6	2	V805000210	BOLT, TORX 5		Slow-moving
7	1	V104002390	GASKET,EXHAUST		Fast-moving
8	1	V805000300	BOLT, TORX 5		Slow-moving
9	1	A320001290	Exhaust cover, SRM-3020TES		Slow-moving
10	2	V203002550	Screw M5x12		Slow-moving

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 09\_RECOIL\_STARTER\_PULLY

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	A051003340	Starter complete, SRM-3020TES		Medium-moving
2	1	P022050890	Starter Housing SRM-3020TES		
3	1	P022045770	GUIDE, ROPE		Slow-moving
4	2	P022022010	NUT		
5	1	P022008470	DRUM		
6	1	P022008460	PLATE, CAM		
7	1	P022008450	SPRING, DAMPER		
8	1	17722040630	SPRING, REWIND		Medium-moving
9	1	17723661830	SCREW		
10	1	P022050900	Starter rope, SRM-3020TES 3.5x750		
11	1	P022050910	GRIP, STARTER		
12	1	A052000190	PULLEY, ASM STARTER		Slow-moving
13	2	P022008480	PAWL, STARTER		
14	2	17723440630	SPRING, RETURN		Slow-moving
15	2	P022002100	E-RING		Slow-moving
16	3	V805000150	BOLT, TORX 5		Slow-moving
17	1	A127000530	Dust cover starter, SRM-3020TES Y2023-747		Slow-moving
18	1	X562001970	LABEL,SHINDAIWA		Slow-moving


www.emc-motoculture.com

Illustration 10\_GEAR\_CASE\_SHIELD



## Illustration 10\_GEAR\_CASE\_SHIELD


Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100004840	CASE,GEAR ASY		
2	1	V000000260	GEAR SET, BEVEL		Slow-moving
3	1	C534001080	SHAFT, GEAR		Slow-moving
4	1	90081206201	BEARING, BALL		
5	1	90081000629	BEARING, BALL		
6	1	90080000609	BEARING, BALL 609		
7	1	90080300609	BEARING, BALL		
8	1	90070100009	RING, RETAINING(EX)		
9	1	90070600012	RETAINING RING		
10	1	90070200032	CIRCLIP 32		
11	1	90070200025	CIRCLIP 25		
12	1	V340000180	WASHER		Slow-moving
13	1	90022004006	SCREW 4* 6		
14	1	V452001310	SPRING,TORSION		Medium-moving
15	1	90060350008	WASHER		Slow-moving
16	1	61043450031	BOLT 8* 8		Medium-moving
17	1	61031352932	FIXTURE,BLADE		Medium-moving
18	1	61031352132	FIXTURE,BLADE		Slow-moving
19	1	61035256830	PLATE, CUP		
20	1	90072000012	O-RING 12		
21	1	61031452130	PLATE, ADAPTER (L)		Medium-moving
22	1	69922956830	PLATE, COVER		Medium-moving
23	1	61032052130	NUT 10		Medium-moving
24	1	V806000020	BOLT, TORX 6		Slow-moving
25	1	V805000130	BOLT, TORX 5		Slow-moving
26	1	P100010590	SHIELD ASY		Medium-moving
27	1	90056500005	NUT, SQUARE		
28	1	V805000170	BOLT, TORX 5		Slow-moving
29	1	90056200005	LOCKNUT 5		
30	1	C552000200	PLATE, SHIELD		Slow-moving
31	1	9131604010	SCREW		Slow-moving
32	4	V805000260	BOLT, TORX 5		Slow-moving
33	1	P021048940	Protection for line head with cutter, B410TS		
34	1	C554000001	KNIFE,CORD		Medium-moving
35	1	V805000150	BOLT, TORX 5		Slow-moving
36	1	X530000570	LABEL,EYE CATCHER		Slow-moving
37	1	C550000541	SHIELD, BLADE		Medium-moving



## Illustration 11\_MAIN\_PIPE\_HANDLE

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100005430	Linkage, SRM-3020TES		
2	1	89061743130	LABEL,CAUTION		Slow-moving
3	1	89015204930	LABEL, CAUTION		Slow-moving
4	1	C504000050	SHAFT,DRIVE		Slow-moving
5	1	P100007470	HOOK ASY		
6	2	V495001010	BAND		Slow-moving
7	2	V805000140	BOLT, TORX 5		Slow-moving
8	1	C624000020	HANGER,HARNESS		Slow-moving
9	1	V363000320	COLLAR,24		Slow-moving
10	2	V804000020	BOLT, TORX 4		Slow-moving
11	1	P021050970	FRONT HANDLE ASY		
12	1	C400000220	HANDLE,FRONT		Slow-moving
13	1	35164351730	BRACET,HANDLE		Slow-moving
14	4	V805000050	BOLT, TORX 5		Slow-moving
15	4	90050000005	NUT		

www.emc-motoculture.com




www.emc-motoculture.com

## Illustration 12\_THROTTLE

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	P100007550	THROTTLE ASY		
2	1	C450000780	Throttle, M262S		Slow-moving
3	1	17804342230	SPRING, THR. RETURN		Medium-moving
4	1	C460000370	LOCKOUT, THROTTLE		Slow-moving
5	1	C461000000	LATCH, THROTTLE		Slow-moving
6	1	17801352630	SPRING, THR. LOCK		Medium-moving
7	1	V805000060	BOLT, TORX 5		Slow-moving
8	3	V805000170	BOLT, TORX 5		Slow-moving
9	4	90050000005	NUT		
10	1	C461000110	Throttle lockout, M262S		Slow-moving
11	1	V452000120	SPRING, TORSION		Medium-moving
12	1	A440003030	SWITCH, ON OFF		Slow-moving
13	1	V475009310	TUBE		Slow-moving
14	1	V430004940	CABLE, BOWDEN		Medium-moving
15	1	90050200006	NUT		
16	1	90051800006	NUT, FLANGE		
17	2	V420000960	CUSHION		Medium-moving
18	2	P021050990	HANDLE FIXTURE ASY		
19	4	V805000170	BOLT, TORX 5		Slow-moving

www.emc-motoculture.com



www.emc-motoculture.com

## Illustration 13\_ACCESSORIES

---

Nbre	Qté	Code	Désignation	Fichier joint	Recommended Stock Item
1	1	30100146732	HARNESS, SHOULDER		Medium-moving
2	1	89541566630	TOOL,BOX SPANNER		Slow-moving
3	1	X605000170	TOOL,L WRENCH		Slow-moving
4	1	X606000080	TOOL,BAR		Slow-moving
5	1	P100008860	SAW BLADE SHIELD		
6	4	V805000410	BOLT, TORX 5		Slow-moving

[www.emc-motoculture.com](http://www.emc-motoculture.com)